

Collection:

Installation manual for:

LD5026 D16"H20"L3

Installation instructions:

- 1.Black wire from ceiling(junction box) attaches to "L"wire from the fixture.
- 2. White wire from ceiling(junction box) attaches to "N"wire from the fixture.
- 3."E" wire from the fixture is attaced to the mounting bracket and an additional "E" wire from the mounting bracket must be secured to the junction box.
- 4. Secure mounting bracket to the junction box.
- 5.Insert screws(P2) in side of top unit the mounting bracket.
- 6. Fix the loop (P3) to screw tube, then cover the canopy (P4) and fix it by canopy ring(P5).
- 7.Install the bulbs(not included) into the lamp fixture.

8. Fix the metal bottom cover(P19) into the crystal

frame(P18).

The end!

"N" = Neutral wire
"E" = Ground wire

PARTS LIST

IIIO OIII.	
Junctio	n box
	P1
	P2
	P3
	P4 —
	P5
	P6 ————————————————————————————————————
	Pi —
	P8 ————————————————————————————————————
	V 7
	P9
	P10 P11
	P12 P13
	P13 P14 P14 P15
	P16
	P17
	P18
	110
	P19
#• # •• · ·	V 1
"L" = Hot wire	- I

part	picture	Description	O+	Check	13.4
pert	brernie		qty	CHECK	118t
P1		LA" Mounting bracket	1		
P2	_	5/32-32 Screw	2		
P3		Canopy loop (Canopy part)	1		
P4		25.1° canopy plat	1		
P5		Canopy ring (Canopy part)	1		
P6		L59"CHAINO4P Plain Design	1		
P7	\	ground wire	1		
P8	\	Power Cord 79" SPT-1-18# Brown	1		
P9	Q	V1.5"*H1.7" Quick link	1		
P10		metal top cover	1		
P11	C C	direction joint	1		
P12		D2"#H1.2" Terminal Block	1		
P13	Ď	Lamp arm	3		
P14		D1.2"*L2" metal lampcap	3		
P15		E12 lampholder	3		
P16		Disk	1		
P17	٥	finial	1		
P18		Ø16″ crytal frame	1		
P19	W	metal bottom cover	1		