

Collection

### BIRKIN Article

# BR205\_2


Description


#### Monohole washbasin mixer complete with drain





Dimensions





<sup>Cartridge</sup> Ceramic headwork	Hoses Inox hoses G3	Hoses Inox hoses G3\8" female 400 mms long		
Aerator	Flow Rate (+/-10%)			
M24x1	1 BAR 10.3 l\m	2 BAR 14.7 l∖m	3 BAR 18.2 l∖m	
Production	Material			
Main body is a single casted pieces	BRASS According to CuZn35Pb2AI-B (CB752S) Max Lead content: 1.36%			

**P.IVA** 01785230986 capitale sociale €420.000,00 i.v. www.weareib.it





	Parts list			
ELEM.	CODE	DESCRIPTION	QTÀ	
1	AQ0014947	Marble cover Ø55 H32	2	
2	AQ0015558	Screw Ø7.1 M6 H9 dark gray	2	
3	AQ0002160	Screw M4x10	2	
4	AQ0006586	OR 25.12x1.78 NBR 70 SH	4	
5	AS0012526	Handle Ø29.9 H19	2	
6	AC0012684	Headwork's cover Ø27 Ø44 H14	2	
7	AQ0002135	Ceramic headwork 90° left	1	
8	AC0012413	Washbasin mixer monohole	1	
9	AQ0014995	Rubber Ø23 Ø20.5 Ø16 H3.3 NBR 60	1	
10	AQ0000020	Aerator M24 x 1 perlator honeycomb (40200503301)	1	
11	AQ0003930	Ceramic headwork 90° right	1	
12	AQ0000932	Inox hose M10x1 G3/8" F L400	2	
13	AQ0009171	Fixing set	1	
14	AQ0009837	Simple rapid waste 1"1/4	1	



**T.** +39 030 802101 **F.** +39 030 803097 info@weareib.it **P.IVA** 01785230986 capitale sociale €420.000,00 i.v. www.weareib.it





# WARRANTY

All IB Rubinetterie SpA products are warrented for 10 years from the date of purchase, for the following cases:

- Defects of casting, porosity and chrome plating.
- Operating defects caused by incorrect fabrication.

The warranty provides for repair or replacement of products with fabrication defects recognized by our technical office. There is no other type of compensation anche the merchandise must be returned FOB our werehouse. The warranty only cover surface defects (scartches, dings, etc.) on fitting that have not been installed and used, returned in its original packaging with all components. O-ring, gasket seals and components subject to wear proportional to use are warranted for 2 years.

## The warranty is void in the following cases:

Error installing and putting the product into service.

Deterioration of finisched surfaces due to use of cleaning products containing acids or abrasive substances. Deterioration of surface with finishes other than chrome plating. Their durability is, in fact, dependent on the user's care and gentleness of use.

Deterioration of the fitting due incorrect installation.

Improper repairs and maintenance performed without the company's prior authorization.

The warranty from IB Rubinetterie SpA is not renewable.

## Cleaning

We recommanded cleaning the finish surfaces with water and soap, using a soft cloth. Do not use detergents that cointain hydrochloric acid or abrasive substances.



**IB RUBINETTERIE** s.p.a via dei Pianotti 3/5 25068 Sarezzo (BS) - Italy - **T.** +39 030 802101 **F.** +39 030 803097 info@weareib.it **P.IVA** 01785230986 capitale sociale €420.000,00 i.v. www.weareib.it



